# BRIDGE DECK EXPANSION DEVICES

Herbert N. Swanson Colorado Department of Highways 4201 East Arkansas Avenue Denver, Colorado 80222

Interim Report September, 1983

Prepared in cooperation with the U. S. Department of Transportation Federal Highway Administration



The contents of this report reflect the views of the authors who are responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official views of the Colorado Department of Highways or the Federal Highway Administration. This report does not constitute a standard, specification, or regulation.

#### **Technical Report Documentation Page**

•			recunical Keport L	ocumentation rag
1. Report No.	2. Government Acces	sion No.	3. Recipient's Catalog N	lo,
CDH-DTP-R-83-11				
4. Title and Subtitle			5. Report Date	***************************************
	** : : : : : : : : : : : : : : : : : :	L	September 1983 6. Performing Organizati	3
Bridge Deck Expansion Dev	ices		6. Performing Organizati	on Code
		-	8. Performing Organizati	on Report No.
7. Author(s)			o. I endining organizati	on napo.
Herbert N. Swanson	ofer Wellering		CDH-DTP-R-83-1	1
9. Performing Organization Name and Addres	3.5		10. Work Unit No. (TRAI	
Colorado Department of Hi	ghways	0.60	11. Contract or Grant No	
4201 E. Arkansas Ave. Denver, CO 80222			1587A	*
Denver, co 80222			13. Type of Report and F	eriod Covered
12. Sponsoring Agency Name and Address			· ·	
Colorado Department of Hi	ghways		22 12 12	
4201 E. Arkansas Ave.		· 1	Interim 14. Sponsoring Agency C	ada .
Denver, CO 80222			. sponsoring Agency C	.000
15. Supplementary Notes				
Prepared in cooperation w	ith the U.S. D	epartment of Tra	insportation,	
Federal Highway Administra	ation.			
16. Abstract			<u> </u>	
expansion devices for use measurements during constra device to remain water to the success of the device the most important factors an expansion joint. Neoporture joints whenever posperform well, however, fur are made.	ruction and po- tight is the me Proper insta s which will u rene compressionsible. On flo	st constructions ost important quallation during attimately determ on joint seals a ex joints have a	to The ability wality used to do construction is ine the success are recommended also been shown	of etermine one of of for to
				•
		w.		
			(4)	
4				
		10 0		
7. Key Words		18. Distribution Statements No restricti		mont :
Structure, Expansion		:	to the public	(N.D. 44 D.)
			Technical Info	
			ingfield, Virgi	
			170. X	
9. Security Classif. (of this report)	20. Security Class	if. (of this page)	21- No. of Pages	22. Price
	- 1		1	I

# TABLE OF CONTENTS

INTRODUCT10	N.	٠	÷	÷	*	٠	٠			•	٠	•	٠	*	٠	٠		0 (0	•	٠	×		•		•	٠	•				•	•		
INSTALLATIO	N.		٠	e		٠			. 2	• :		•				,	:,	ss 30				٠		٠						ě				4
PERFORMANCE	š							•	•					- 1			•	٠		٠		٠	٠							٠				13
costs	•	•		. 110	•	•	٠	•	•	·					<b>8</b> 7 5	•	٠	٠	•		,		•	•	1 39	ē 1	ě	*	•	5	•		. :	16
CONCLUSIONS	ANI	) I	REC	400	am.	SN1	DĀ	TI	01	vs.		٠																					. 8	16

#### INTRODUCTION

This interim report documents a study which was initiated to evaluate various promising bridge deck expansion joints. The final report will be prepared and distributed after sufficient evaluations (at least three years on each device) are made.

Expansion joints have been a major problem in bridge design, construction, and maintenance for many years. Numerous expansion devices used as standards in the past have proved insufficient because of their susceptibility to damage and failure due to snowplows, increased traffic loading, and intrusion of water debris through the joints. Many of these problems were the result of poor design or placement of the expansion device. In areas where deicing chemicals are used to prevent bridge and roadway icing, leakage through joints has caused serious structural damage to concrete bridge seats, piers, abutments, and steel support members.

FHWA Notice N 5140.12 dated April 10, 1978 concerning the final report from the National Experimental and Evaluation Program (NEEP), Project Number 11, gave guidelines for selecting bridge deck expansion devices on Federal-Aid Highways. Using this project as a guide, promising expansion devices were incorporated into the study.

Six types of these devices were included in the original study proposal. The project has been expanded several times to include others as new project plans and devices were developed.

Thirteen (13) different systems have been included in the study on twenty-one structures to seal 128 joints. Table A is a list of the expansion devices. The structure numbers, project numbers, and location where each was or will be placed. The dates submitted, approved for use by the FHWA, the construction date, the date awarded and the date completed are also included in Table A.

TABLE A

EVALUATION OF BRIDGE DECK EXPANSION DEVICES

CATEGORY II STUDY

March 16, 1983

Structure Number	Project Number	Location	Date Submitted	Date Approved	Bids Awards	Date Completed
I-17-GU	FCU 083-1(11)	SH 115 to B Street	3/16/78	4/25/78	5/ 4/78	. 8/79
F-12-AL					A SERVICE AND ADDRESS OF THE PROPERTY OF THE P	9/79
F-8-Q						5/80
F-8-R	I 70-2(79)			8/31/78		5/80
E-18-AM	I 76-1(53)	I 76 Lochbuie	9/14/78	10/ 5/78	2/28/80	6/81
P-5-S	FC 160-2(22)	SH 160 South of Durango	9/14/78	10/ 5/78	11/16/78	10/79
E-16-KB	I 76-1(56)	I 76 Wadsworth to Marshal	10/24/78	12/ 8/78	9/ 6/79	8/80
E-16-KC	IR 76-1(61)	I 76 Wadsworth to Marshal	5/22/79	7/12/79	9/ 6/79	9/81
E-17-FX	I 70-4(79)	46th Avenue Viaduct-WB	11/21/78	12/14/78	12/21/78	9/79
E-17-FV	IR 70-4(73)	46th Avenue Viaduct-WB	11/21/78	12/14/78	12/21/78	9/79
E-17-FU	IR 70-4(73)	46th Avenue Viaduct-WB	11/21/78	12/14/78	12/21/78	9/79
E-17-FW	IR 70-4(73)	46th Avenue Viaduct-WB	11/21/78	12/14/78	12/21/78	9/79
H-17-CQ	I 25-2(132)	I 25 at Perry Park Road	3/16/79	5/ 1/79	9/13/79	8/80
E-17-FX	I 70-4(82) IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/3/79	1/15/80	7/80
E-17-FX	IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/ 3/79	1/15/80	7/80
E-17-FX	IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/ 3/79	1/15/80	7/80
E-17-FV	IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/ 3/79	1/15/80	7/80
E-17-FV	IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/ 3/79	1/15/80	7/80
E-17-FW	IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/ 3/79	1/15/80	7/80
E-17-FX	IR 70-4(80)	46th Avenue Viaduct-EB	9/11/79	10/ 3/79	1/15/80	7/80
E-18-A0	I 76-1(53)	SH 7 to Hudson	9/20/79	10/ 3/79	3/20/80	
D-18-BN	I 76-1(55)	I 76 - SH 7 to Hudson	10/15/79	10/25/79	12/18/80	9/81
E-17-MD	CC12-1642-02 87-01	56th Avenue at Sand Creek	3/11/80	3/25/80	8/28/80	7/81
D-16-CW	TOFCU 157-1(1)	47th St. Pky. over Boulder Cr.	9/25/80	10/16/80	7/ 1/82	11/82
F-16-JX	BRF 040-4(9)	Colfax Viaduct	1/14/83	2/11/83		
E-17-II E-17-IC	IR 270-6(13) % IR 270-6(14)	I 270 E.B. over Brighton & York St. over I 270	3/16/83 3/16/83			
	Number I-17-GU F-12-AL F-8-Q F-8-R E-18-AM P-5-S E-16-KB E-16-KC E-17-FX E-17-FV E-17-FV E-17-FW H-17-CQ E-17-FX E-17-FX E-17-FX E-17-FX E-17-FX E-17-FX E-17-FX E-17-FV E-17-FV E-17-FV E-17-FV E-17-FX E-17-	Number         Number           I-17-GU         FCU 083-1(11)           F-12-AL         I 70-2(69)           F-8-Q         I 70-2(79)           F-8-R         I 70-2(79)           E-18-AM         I 76-1(53)           P-5-S         FC 160-2(22)           E-16-KB         I 76-1(56)           E-16-KC         IR 76-1(61)           E-17-FX         I 70-4(79)           E-17-FV         IR 70-4(73)           E-17-FW         IR 70-4(73)           E-17-FW         IR 70-4(80)           E-17-FX         IR 70-4(80)           E-17-FX         IR 70-4(80)           E-17-FV         IR 70-4(80)           E-17-FW         IR 70-4(80)           E-17-FW         IR 70-4(80)           E-17-FX         IR 70-4(80)	Number	Number   Number   Location   Submitted	Number   Number   Location   Submitted   Approved    -17-GU   FCU 083-1(11)   SH 115 to B Street   3/16/78   4/25/78    -12-AL   I 70-2(69)   I-70 at Corral Creek   3/6/78   4/25/78    -18-8-Q   I 70-2(79)   I 70 Dotsero to Gypsum   6/5/78   8/31/78    -18-R   I 70-2(79)   I 70 Dotsero to Gypsum   6/5/78   8/31/78    -18-AM   I 76-1(53)   I 76 Lochbuie   9/14/78   10/5/78    -18-BAM   I 76-1(56)   I 76 Wadsworth to Marshal   10/24/78   12/8/78    -18-16-KB   I 76-1(56)   I 76 Wadsworth to Marshal   10/24/78   12/8/78    -18-17-FX   I 70-4(70)   46th Avenue Viaduct-WB   11/21/78   12/14/78    -17-FY   IR 70-4(73)   46th Avenue Viaduct-WB   11/21/78   12/14/78    -17-FW   IR 70-4(80)   46th Avenue Viaduct-BB   9/11/79   5/1/79    -17-FX   IR 70-4(80)   46th Avenue Viaduct-EB   9/11/79   10/3/79    -17-FX   IR 70-4(80)   46th Avenue Viaduct-EB   9/11/79   10/3/79    -17-FY   IR 70-4(80)   46th Avenue Viaduct-EB   9/11/79   10/3/79    -17-FW   IR 70-4(80)   46th Avenue Viaduct-EB   9/11/79	Number Number Location Submitted Approved Awards I-17-GU FCU 083-1(11) SH 115 to B Street 3/16/78 4/25/78 5/ 4/78 F-12-AL I 70-2(69) I-70 at Corral Creek 3/ 6/78 4/25/78 5/11/78 F-8-Q I 70-2(79) I 70 Dotsero to Gypsum 6/ 5/78 8/31/78 3/ 1/79 F-8-R I 70-2(79) I 70 Dotsero to Gypsum 6/ 5/78 8/31/78 3/ 1/79 E-18-AM I 76-1(53) I 76 Lochbule 9/14/78 10/ 5/78 2/28/80 P-5-S FC 160-2(22) SH 160 South of Durango 9/14/78 10/ 5/78 1/16/78 E-16-KB I 76-1(56) I 76 Wadsworth to Marshal 10/24/78 12/ 8/78 9/ 6/79 E-16-KC IR 76-1(61) I 76 Wadsworth to Marshal 5/22/79 7/12/79 9/ 6/79 E-17-FX I 70-4(79) 46th Avenue Viaduct-WB 11/21/78 12/14/78 12/21/78 E-17-FV IR 70-4(73) 46th Avenue Viaduct-WB 11/21/78 12/14/78 12/21/78 E-17-FW IR 70-4(73) 46th Avenue Viaduct-WB 11/21/78 12/14/78 12/21/78 E-17-FW IR 70-4(73) 46th Avenue Viaduct-WB 11/21/78 12/14/78 12/21/78 H-17-CQ I 25-2(132) I 25 at Perry Park Road 3/16/79 5/ 1/79 9/13/79  E-17-FX I 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FX IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FV IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FV IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FV IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FV IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FV IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FV IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FW IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FW IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FW IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FW IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-17-FW IR 70-4(80) 46th Avenue Viaduct-EB 9/11/79 10/ 3/79 1/15/80 E-18-A0 I 76-1(53) SH 7 to Hudson 10/15/79 10/ 3/79 1/15/80 E-18-A0 I 76-1(53) SH 7 to Hudson 10/15/79 10/ 3/79 1/15/80 E-18-A0 I 76-1(55) I 76 - SH 7 to Hudson 10/15/79 10/ 3/79 1/15/80 E-17-MD CC12-1642-02 56th Avenue 4 Sand Creek 3/11/83 2

The objectives of the study is to evaluate various types of bridge deck expansion devices with the intent of finding the most maintenance free and waterproof bridge expansion device for use in Colorado.

The evaluation procedures included inspections and measurements during construction and at least twice a year for a minimum of three years. Wear or damage to the expansion device is often sufficient criteria to determine failure. The ability of an expansion device to remain water tight is the most import quality used to determine the success of the device. The underside of these expansion joints was inspected at least once a year during inclement weather to detect any leaks.

This interim report covers the expansion devices listed in Table B which have been evaluated for three years or more. This list of expansion devices will be removed from the list in Table A and the remaining list will continue to be evaluated under this experimental project. Occasional inspections of the devices in Table B are planned at state expense as a general follow up.

#### INSTALLATION

The installation of expansion joints is probably the most critical factor in long term successful performance. The measurements and layout for forming and preparation of the expansion joints site are very important to facilitate ease of installation, to provide proper expansion - contraction dimensions and to provide a recessed profile which ultimately protects the device from traffic and snow removal equipment. Project engineers and inspectors should see that the details in plans are followed closely and be very critical about expansion joints since they are a key element in the longevity of the structure.

#### DELASTIFLEX AT DOTSERO

The four Delastiflex joints placed on two structures near Dotsero were exceptionally good installations. The joints were placed and covered with a 1/8" fiber board prior to the paving of the final riding surfaces of the deck and approaches. This fiber board was worn off by traffic and gave good clearance for the entire joint.




Photo #1 Delastiflex joint at Dotsero

The aluminum frame had been installed.




Photo #2

I-70 Over Corral Creek

Delastiflex Expansion Device with Neoprene Installed.

W End Structure F-12-AL

The installation of the delastiflex expansion joint on I-70 over Corral Creek was accomplished without any problems. The finished approach, joint and structure were all on an even grade and had a good appearance.




Diagram A

#### ACME STRIP SEAL



Photo 3

Acme Strip Seal

1-17-GU SH 83, 115 to B Street, Colorado Springs

Rubber extrusion being installed using screwdriver, steel bar and special tool.

There was some form slippage when the deck was poured on I-17-GU in Colorado Springs.

The "A" dimensions were within tolerances, but workmen had some difficulty installing the membrane. The final product was okay and looked good.




Diagram B




Diagram C

This general diagram is used for Fel-Pro, Onflex, Waboflex, and Transflex expansion joints. Dimensions are specified for each joint and each type of device on an individual basis.




Photo 4

Workmen installing Fel Pro at I-25 over Perry Park Road.

The placement of Fel-Pro was completed with no major problems. The expansion joint was completed at or very near the finished grade and appeared to be okay at the completion of the project.

# TRANSFLEX




Photo 5
Transflex 400A on 1-70 Viaduct.





Photo 6

Transflex 250 on 1-70 Viaduct

Both sizes of Transflex looked good just after installation, however, the surface was flushed with the finished grade.

#### WABOFLEX




# Photo 7

Waboflex SR2A on 1-70 Viaduct.

This joint was also finished at the same grade as the finished roadway. Installation went well and the joint looked okay.

# ONFLEX



# Photo 8

Onflex was placed on several joints on the 46th Avenue Viaduct.

Special Y joints were constructed to accommodate adjoining structures at ramps and railroad overpasses.




Diagram D Onflex

The center of the aluminum was damaged by equipment during the installation of Onflex 45 at Durango. There was also a variation of 3/16" in the 'A' dimension across the length of the joint. There has been no subsequent damage and this is not believed to be the cause of subsequent leaks.




Photo 9

Aluminum damaged on this Onflex expansion joint device at Durango.




Photo 10

I-70 Viaduct WB Experimental Joint #39

Neoprene Compression joint seal. A metal channel and bolts are used to maintain the proper "A" dimension.

An epoxy glue serves as a lubricant while the neoprene sealer is forced into place. The contractor encountered no problems with most of these joints on the 46th Avenue Viaduct. The metal angle iron parts were installed too close together on three joints and a special order for smaller neoprene strips was made.




Diagram E

#### PERFORMANCE

This report deals only with those expansion devices which have been in place for three years or more. Table B is a list of these devices, their locations, cost per lineal foot, leaks, and damage. The major factor in determining the failure of an expansion device is whether it leaks or not. Special efforts were made to inspect the joints during a rainy period to determine leaks. Compression joint seals, which are a standard for comparison, show only a 4% failure of 72 joints on the 46th Avenue Viaduct. Of the various types of expansion devices installed statewide, fifty-eight percent (58%) of the Onflex joints have failed and 50% of both Waboflex and Transflex have failed by this criterion. Both Acme Strip seal joints on one structure have not leaked. The one Fel-Pro joint has been worn by traffic and snow removal equipment. There are several serious leaks in this joint. Delastiflex was used on three structures, one of which shows severe damage and leaks for 335 failure rate. The placement of Delastiflex on the two structures at Dotsero were exceptionally good leading to the positive results. A major observation is that most expansion joints can work effectively if they are properly installed.

Joint installations placed near the same grade as the finished roadway are subject to damage by traffic and snow removal equipment. Heavy traffic volumes, especially when a large percent of the vehicles are using studded snow tires or chains, soon wear the pavement surface to or below the level of the expansion joints. Moderate to heavy damage has been observed in such instances. Severe damage can be expected in high snowfall areas where plows and blades pass over the joints many times a day for more than 150 days a year. This extreme equipment use, high traffic volume, and adverse environment combine to produce the harshest test for any structural component of a highway.

TABLE B
EVALUATION OF BRIDGE DECK EXPANSION DEVICES

# CATEGORY II STUDY

			Cost Per		Dam	age
Expansion Device	<u>Joints</u>	Location	Lin. Ft.	Leaks	Const.	Snow Plow
Acme Strip Seal	(2)	SH 115 to B Street	\$123	No		No
Delastiflex	(2)	I-70 at Corral Cree	k \$ 83	Yes	Yes	Severe
Delastiflex	(2)	I-70 Dotsero to Gyp	sum \$ 88	No		Light
Delastiflex	(2)	I-70 Dotsero to Gyp	sum \$ 88	No		No
Onflex 45	(2)	SH 160 So. of Duran	go \$173	Yes	Yes	No
FEL-PRO	(1)	I-25 at Perry Park	Rd. \$200	Yes		Moderate
Compression Joint	(72)	46th Avenue Viaduct	\$100	4%		Heavy
Seal						
Onflex 25	(8)	46th Avenue Viaduct	\$200	75%		Light
Onflex 45	(10)	46th Avenue Viaduct	\$200	40%		Light
WABOFLEX SR2A	(2)	46th Avenue Viaduct	\$220	50%		Heavy
TRANSFLEX	(1)	46th Avenue Viaduct	\$220	0		No
TRANSFLEX 250	(3)	46th Avenue Viaduct	\$220	66%		Moderate

The longitivity and wear of all these experimental joints can be correlated to installation and high traffic volume and snow removal equipment. Most of the joints evaluated in this report have only been in service for three to four years, yet many have failed. More care and attention to details during installation would save a considerable amount of repair rehabilitation or replacement which is sometimes necessary long before the expected service life on many structures.




Photo #2, snowplow damage to the aluminum rail of an Onflex 45 joint number 8 on the westbound 46th Avenue Viaduct. This joint now has major leaks during wet weather.

The sand and debris is typical in all recessed parts of all of the experimental expansion joints.

#### COSTS

It can easily be seen on Table B that Delastiflex and compression joint seal are the least costly and they have also provided the most successful expansion joints of those on this list. The costs were taken from bid tabs which include the materials, labor and other expences for the joints in place on the job.

# CONCLUSION AND RECOMMENDATIONS

The most important factor which will ultimately determine the success of an expansion joint is proper installation during construction. All measurements have shown that attachments and anchors are vary important in the final alignment and position of the expansion joint. A finished joint which is recessed 1/8" to 1/4" and has good approach protection will most likely not be damaged by traffic or snow removal equipment. Rigid inspection during installation is essential. Most expansion joints can work effectively if they are installed properly, however, the results of this study, which includes only those expansion joints on the experimental list (Table B) indicates that compression joint seals, acme strips seal, Onflex, and Delastiflex have performed the best.

None of the devices in table B can be classified as acceptable or unacceptable at this time because the cause of failures have not been conclusively proven to be related to installation, snow plow, traffic or simply the failure of the device. CDOH will continue to use compression joint seals where the movements are less than 2" and continuous strip seals such as onflex and acme where movements are less than 4". Even though they don't have a good performance record, Waboflex and Transflex will be used when movements are between 4" and 13" because they are the only products on the market that can be used for these large movements.

Most of the expansion joints on the 46th Avenue Viaduct are not located over abutments or piers, therefore, water and leaking minerals cause very little structural damage to these members.

Four other expansion joints Gen strip, Wabo-Alu Strip, Acme TR300 and Evazote are still under evaluation. Two additional installations of Onflex as well as elastomeric concrete end dams and strip seals are also still under evaluation. A final report will document the results on these items and make further recommendations. Each experimental expansion joint must be evaluated for at least three years. Some of the experimental features listed on Table A have not yet been installed, therefore, a final report will not be written before the summer of 1987.